

## Abstract

A print job is partitioned into sub-jobs or "batches" to shorten the turnaround time for completing the processing of the print job. The sizes of the batches are chosen so as to minimize the turnaround time. The batch sizes are optimized based on factors affecting the turnaround time. The batches may be processed concurrently in a pipelined fashion to minimize the turnaround time.